




3-117
Medley
3.10

3 10 0016

November 7, 1990



Ms. Angela Gorman
South Carolina Department of Health
and Environmental Control
Division of Hydrogeology
Bureau of Solid and Hazardous Waste Management
2600 Bull Street
Columbia, SC 29201

Subject: Medley Farm Site Remedial Investigation
Phase II Ground Water Monitoring Wells
SEC Job No. G-8026

Dear Ms. Gorman:

Pursuant to the provisions of Section 44-55-40 of the 1976 South Carolina Code of Laws and the Department of Health and Environmental Control's Regulations R.61-71, the following information is herein submitted for all ground water monitoring wells installed during Phase I and II of the Remedial Investigation performed at the Medley Farm site located in Gaffney, South Carolina:

- Monitoring well construction details
- Monitoring well locations in accordance with the South Carolina State Planar Coordinate System.
- Surveyed "top of casing" elevations of each monitoring well in accordance with the National Geodetic Vertical Datum.
- A topographic plan of the Medley Farm Site including surveyed monitoring well locations.


Ms. Angela Gorman
November 7, 1990
Page 2

3 10 0017

If you have any questions regarding this information, please do not hesitate to call us at (803) 234-3000.

Sincerely,

Sirrinc Environmental Consultants, Inc.



James S. Chamness, P.G.
Project Manager

Enclosures

JSC/de

cc: Mr. Jon Bornholm - EPA Region IV
Mr. Gary Stewart - SCDHEC
Mr. Les Oakes
Mr. Ted Volario
Mr. Philip Connors
Project File